

ENGINEERING DRAWING

(NSQF)

1 YEAR

Revised Syllabus - 2022

Group 9

Group 9 CTS Trades Covered

Sheet Metal



Directorate General of Training

DIRECTORATE GENERAL OF TRAINING
MINISTRY OF SKILL DEVELOPMENT & ENTREPRENEURSHIP
GOVERNMENT OF INDIA



**NATIONAL INSTRUCTIONAL
MEDIA INSTITUTE, CHENNAI**

Post Box No. 3142, CTI Campus, Guindy, Chennai - 600 032

Engineering Drawing (NSQF) - 1 Year
Group 9 - Engineering Trade
As per Revised syllabus 2022 under CTS

Developed & Printed by



National Instructional Media Institute

Post Box No.3142

Guindy, Chennai - 600032

INDIA

Email: chennai-nimi@nic.in

Website: www.nimi.gov.in

Copyright © 2022 National Instructional Media Institute, Chennai

First Edition : May 2022

Copies : 500

Rs. /-

FOREWORD

The Government of India has set an ambitious target of imparting skills to 30 crores people, one out of every four Indians, by 2020 to help them secure jobs as part of the National Skills Development Policy. Industrial Training Institutes (ITIs) play a vital role in this process especially in terms of providing skilled manpower. Keeping this in mind, and for providing the current industry relevant skill training to Trainees, ITI syllabus has been recently updated with the help of comprising various stakeholder's viz. Industries, Entrepreneurs, Academicians and representatives from ITIs.

The National Instructional Media Institute (NIMI), Chennai, has now come up with instructional material to suit the revised curriculum for **Engineering Drawing 1 Year NSQF Group 9 - Engineering Trade** under CTS will help the trainees to get an international equivalency standard where their skill proficiency and competency will be duly recognized across the globe and this will also increase the scope of recognition of prior learning. NSQF trainees will also get the opportunities to promote life long learning and skill development. I have no doubt that with NSQF the trainers and trainees of ITIs, and all stakeholders will derive maximum benefits from these IMPs and that NIMI's effort will go a long way in improving the quality of Vocational training in the country.

The Executive Director & Staff of NIMI and members of Media Development Committee deserve appreciation for their contribution in bringing out this publication.

Jai Hind

SHRI. ATUL KUMAR TIWARI., I.A.S.,
Director General/Addl. Secretary
Ministry of Skill Development & Entrepreneurship,
Government of India.

New Delhi - 110 001

PREFACE

The National Instructional Media Institute(NIMI) was set up at Chennai, by the Directorate General of Training, Ministry of skill Development and Entrepreneurship, Government of India, with the technical assistance from the Govt of the Federal Republic of Germany with the prime objective of developing and disseminating instructional Material for various trades as per prescribed syllabus and Craftsman Training Programme(CTS) under NSQF levels.

The Instructional materials are developed and produced in the form of Instructional Media Packages (IMPs), consisting of Trade Theory, Trade Practical, Test and Assignment Book, Instructor Guide, Wall charts, Transparencies and other supportive materials. The above material will enable to achieve overall improvement in the standard of training in ITIs.

A national multi-skill programme called SKILL INDIA, was launched by the Government of India, through a Gazette Notification from the Ministry of Finance (Dept of Economic Affairs), Govt of India, dated 27th December 2013, with a view to create opportunities, space and scope for the development of talents of Indian Youth, and to develop those sectors under Skill Development.

The emphasis is to skill the Youth in such a manner to enable them to get employment and also improve Entrepreneurship by providing training, support and guidance for all occupation that were of traditional types. The training programme would be in the lines of International level, so that youths of our Country can get employed within the Country or Overseas employment. The **National Skill Qualification Framework (NSQF)**, anchored at the National Skill Development Agency(NSDA), is a Nationally Integrated Education and competency-based framework, to organize all qualifications according to a series of **levels of Knowledge, Skill and Aptitude**. Under NSQF the learner can acquire the Certification for Competency needed at any level through formal, non-formal or informal learning.

The **Engineering Drawing** 1 Year NSQF Group 9 - Engineering Trade under CTS is one of the book developed by the core group members as per the NSQF syllabus.

The **Engineering Drawing** 1 Year NSQF Group 9 - Engineering Trade under CTS as per NSQF) is the outcome of the collective efforts of experts from Field Institutes of DGT, Champion ITI's for each of the Sectors, and also Media Development Committee (**MDC**) members and Staff of **NIMI**. NIMI wishes that the above material will fulfill to satisfy the long needs of the trainees and instructors and shall help the trainees for their Employability in Vocational Training.

NIMI would like to take this opportunity to convey sincere thanks to all the Members and Media Development Committee (MDC) members.

Chennai - 600 032

EXECUTIVE DIRECTOR

ACKNOWLEDGEMENT

The National Instructional Media Institute (NIMI) sincerely acknowledge with thanks the co-operation and contribution of the following Media Developers to bring this IMP for the course **Engineering Drawing 1 Year Group 9 - Engineering Trade** as per NSQF.

MEDIA DEVELOPMENT COMMITTEE MEMBERS

| | | |
|--------------------------|---|--|
| Shri. M. Sangara pandian | - | Training Officer (Retd.) CTI, Govt. of India, Guindy, Chennai - 32. |
| Shri. G. Sathiamoorthy | - | Jr. Training Officer - sg (Retd.) Govt. I.T.I, Trichy, DET - Tamilnadu. |
| Smt. M.V. Vijayavalli | - | Assistant Training Officer, Govt. I.T.I., Guindy, DET - Tamilnadu. |

NIMI CO-ORDINATORS

| | | |
|------------------------|---|--|
| Shri. Nirmalya Nath | - | Deputy General Manager, NIMI, Chennai - 32. |
| Shri. G. Michael Johny | - | Manager, NIMI, Chennai - 32. |

NIMI records its appreciation of the **Data Entry, CAD, DTP Operators** for their excellent and devoted services in the process of development of this IMP.

NIMI also acknowledges with thanks, the efforts rendered by all other staff who have contributed for the development of this book.

INTRODUCTION

Theory and procedure along with the related exercises for further practice

This book on theory and procedure along with related exercises contains theoretical information on **1 Year Engineering drawing** NSQF (Revised syllabus 2022 Group 9 - Engineering Trade) and procedure of drawing/ sketching different exercise for further practice are also available. Wherever required, BIS specification has been used.

Exercise for further practice

The practice exercise is given with Theory and procedure for 1st Year book made obsolete as it was felt that, it is very difficult to work in workbook using drawing instruments. It is well known fact that, any drawing is prepared on suitable standard size of drawing sheets only.

The instructor is herewith advised to go through the instructions given below and to follow them in view of imparting much drawing skill in the trainees.

Acquiring the above said ability and doing small drawings is not a simple task. These books will provide a good platform for achieving the said skills.

Time allotment:

Duration of 1st Year : 40 Hrs

| Sl. No. | Topic | Exercise No. | Time Allotment |
|---------|---|-----------------|----------------|
| 1 | Introduction to Engineering Drawing and Drawing Instruments | 1.1.01 - 1.1.05 | 2 |
| 2 | Lines and Free hand drawing | 1.2.06 - 1.2.09 | 6 |
| 3 | Drawing | 1.3.10 - 1.3.13 | 8 |
| 4 | Dimensioning | 1.4.14 - 1.4.16 | 2 |
| 5 | Concept and Reading of Drawing | 1.5.17 - 1.5.19 | 10 |
| 6 | Symbolic Representation | 1.6.20 | 4 |
| 7 | Reading of Job drawing of related trades | 1.7.21 | 8 |
| | | | 40 Hrs |

Instructions to the Instructors

It is suggested to get the drawing prepared on A4/A3 sheets preferably on only one side. If separate table and chair facility is available for every trainee then it is preferred to use A3 sheets and if the drawing hall is provided with desks then A4 sheets may be used. However while preparing bigger drawings on A4 sheets suitable reduction scale to be used or multiple sheets may be used for detailed and assembly drawings.

First the border and the title block to be drawn only for the first sheet of the chapter. Eg. for conical sections only first sheet will have the title block whereas the rest of the sheets of that chapter will have only borders.

Serial number of sheet and total no. of sheets to be mentioned on each sheet.

The completed sheet to be punched and filled in a box file/ suitable files and preserved by the trainees carefully after the approval of instructor, VP and Principal of the Institute.

The file may be referred by the authority before granting the internal marks at the end of the Year.

LEARNING / ASSESSABLE OUTCOME

On completion of this book you shall be able to

- **Read and apply engineering drawing for different application in the field of work.**

CONTENTS

| Exercise No. | Topic of the Exercise | Page No. |
|--------------|---|----------|
| | Introduction to Engineering Drawing and Drawing Instruments | |
| 1.1.01 | Introduction to engineering drawing and drawing instruments | 1 |
| 1.1.02 | Conventions | 4 |
| 1.1.03 | Sizes and layout of drawing sheets | 5 |
| 1.1.04 | Title block, its position and content | 7 |
| 1.1.05 | Drawing instruments | 11 |
| | Lines and Free hand drawing | |
| 1.2.06 | Lines - Types and applications in drawing | 16 |
| 1.2.07 | Free hand drawing of - Geometrical figures and block with dimension | 22 |
| 1.2.08 | Free hand drawing of - Transferring measurement from the given object to the free hand sketches | 25 |
| 1.2.09 | Free hand drawing of hand tools and measuring tools | 29 |
| | Drawing | |
| 1.3.10 | Drawing of angle & triangle | 35 |
| 1.3.11 | Drawing of circle | 38 |
| 1.3.12 | Drawing of square, rectangle and parallelogram | 40 |
| 1.3.13 | Drawing of ellipse & parabola | 42 |
| 1.3.14 | Drawing of lettering and numbering - Single stroke | 46 |
| 1.3.15 | Drawing of development of surfaces - Introduction | 50 |
| 1.3.16 | Drawing of development of surfaces - Procedure | 52 |
| | Dimensioning | |
| 1.4.17 | Dimensioning - Types of arrow heads and leader line with text | 57 |
| 1.4.18 | Dimensioning - Position of dimensioning (aligned, unidirectional) | 58 |
| 1.4.19 | Practice of dimensioning | 60 |
| | Concept and Reading of Drawing | |
| 1.5.20 | Concept and reading of drawing in - Concept of axes plane and quadrant | 63 |
| 1.5.21 | Concept and reading of drawing in - Concept of orthographic projection and isometric projection | 66 |
| 1.5.22 | Method of 1st angle and 3rd angle projections (Definition and difference) | 72 |
| | Symbolic Representation | |
| 1.6.20 | Symbolic representation - Different symbols used in the sheet metal trade | 74 |
| | Reading of Job drawing of related trades | |
| 1.7.21 | Reading of job drawing related to sheet metal trade | 77 |

SYLLABUS

1 Year

Group 9 - Revised syllabus 2022
Engineering trades under CTS

Duration: 1 Year

CTS Trades Covered: Mason

| S.no. | Syllabus | Time in Hrs |
|-------|--|-------------|
| 1 | Introduction to Engineering Drawing and Drawing Instruments – <ul style="list-style-type: none">• Conventions• Sizes and layout of drawing sheets• Title Block, its position and content• Drawing Instrument | 2 |
| 2 | Lines - Types and applications in drawing Free hand drawing of - <ul style="list-style-type: none">• Geometrical figures and blocks with dimension• Transferring measurement from the given object to the free hand sketches.• Free hand drawing of hand tools and measuring tools. | 6 |
| 3 | Drawing of - <ul style="list-style-type: none">• Angle, Triangle, Circle, Rectangle, Square, Parallelogram, Ellipse & Parabola.• Lettering & Numbering - Single Stroke.• Development of Surfaces | 8 |
| 4 | Dimensioning <ul style="list-style-type: none">• Types of arrowhead• Leader line with text• Position of dimensioning (Unidirectional, Aligned) | 2 |
| 5 | Concept and reading of Drawing in <ul style="list-style-type: none">• Concept of axes plane and quadrant• Concept of Orthographic and Isometric projections• Method of first angle and third angle projections (definition and difference) | 10 |
| 6 | Symbolic representation - <ul style="list-style-type: none">• Different symbols used in the Sheet Metal trade. | 4 |
| 7 | Reading of Job drawing related to Sheet Metal trade. | 8 |
| | Total | 40 |

Introduction to engineering drawing and drawing instruments

Communication

There are many different ways of communicating ideas, information, instructions, requests, etc. They can be transmitted by signs or gestures, by word of mouth, in writing, or graphically. In an industrial context the graphical method is commonly used with communication is achieved by means of engineering drawings.

If oral and written communication only were used when dealing with technical matters, misunderstandings could arise, particularly in relation to shape and size. The lack of a universal spoken language makes communication and understanding even more difficult because of the necessity to translate both words and meaning from one language to another.

However, the universally accepted methods used in graphical communication through engineering drawings eliminate many of these difficulties and make it possible for drawing prepared by a British designer to be correctly interpreted or “read” by, for example, his German, French or Dutch counterparts.

Equally important, the components shown on the drawings could be made by suitably skilled craftsmen of any nationality provided they can “read” an engineering drawing.


Conventionally prepared engineering drawings provide the main means of communication between the “ideas” men (the designers and draughtsman) and the craftsmen (machinists, fitters, assemblers, etc.). For the communication to be effective, everyone concerned must interpret the drawing in the same way. Only then will the finished product be exactly as the designer envisages it.

To ensure uniformity of interpretation, the British Standards Institution has prepared a booklet entitled BS 308:1972, Engineering Drawing Practice. Now in three parts, this publication recommends the methods which should be adopted for the preparation of drawing used in the engineering industry.

The standards and conventions in most common use and hence those required for a basic understanding of engineering drawing are illustrated and explained in this book.

Language

1 It is the media of communication (Fig 1)



EDNSM110111

Conclusion

Effective communication is possible when graphical language is supported by written language/vocal language and vice versa.

Engineering drawing is a language that uses both graphical language and written language for effective communication.

Engineering drawing is a graphical language that also uses written language for effective communication.

The importance of Engineering Drawing

The economic success of any country is mainly dependent on its industrial development. Due to globalization, any industry in our country is expected to be of a global market standard. For the above-mentioned reasons, our Indian products require very high quality for their size, dimension, fit, tolerance, and finish etc.

To produce the best standard product, all the technical personnel (Engineers to Craftsman) in an industry must have a sound knowledge of engineering drawing because engineering drawing is the language of engineers. Engineering drawing is a universal language. Different types of lines make up their alphabets. Technical personnel in any industry, including craftsman, are expected to communicate anything concerning a part or a component by means of drawings involving lines, symbols, conventions, abbreviations etc.

With our spoken languages, it is impossible to express the details of a job or a product. Engineering drawing knowledge and practise are a must for designing or producing a component or part. Even a small mistake in the drawing may reflect very badly on the product. Therefore, reading and doing engineering drawings are very essential for craftsmen and engineers.

A drawing is a graphical representation of an object, or part of it, and is the result of creative thought by an engineer or technician. When one person sketches a rough map in giving direction to another, this is graphic communication. Graphic communication involves using visual materials to relate ideas. Drawings, photographs, slides, transparencies, and sketches are all forms of graphic communication. Any medium that uses a graphic image to aid in conveying a message, instructions, or an idea is involved in graphic communication.

One of the most widely used forms of graphic communication is the drawing. Technically, it can be defined as **"a graphic representation of an idea, a concept or an entity which actually or potentially exists in life"**

Drawing is one of the oldest forms of communicating, dating back even farther than verbal communication. The drawing itself is a method of communicating necessary information about an abstract, such as an idea or concept or a graphic representation of some real entity, such as a machine part, house or tools. There are two basic types of drawings: Artistic and Technical drawings.

Technical drawings

Technical drawings allows efficient communication among engineers and can be kept as a record of the planning process. Since a picture is worth a thousand words, a technical drawing is a much more effective tool for engineers than a written plan.

The technical drawing, on the other hand is not subtle, or abstract. It does not require an understanding of its creator, only on understanding of technical drawings. A technical drawing is a means of clearly and concisely communicating all of the information necessary to transform an idea or a concept in to reality. Therefore, a technical drawing often contains more than just a graphic representation of its subject. It also contains dimensions, notes and specifications.

Fields of use

Technical drawing is the preferred method of drafting in all engineering fields, including, but not limited to, civil engineering, electrical engineering, mechanical engineering and architecture.

Purpose of studying engineering drawing

- 1 To develop the ability to produce simple engineering drawing and sketches based on current practice
- 2 To develop the skills to read manufacturing and construction drawings used in industry.
- 3 To develop a working knowledge of the layout of plant and equipment.
- 4 To develop skills in abstracting information from calculation sheets and schematic diagrams to produce working drawings for manufacturers, installers and fabricators.

Main types of Engineering drawing

Regardless of branch of engineering the engineering drawing is used. However based on the major engineering branches, engineering drawing can be classified as follows: (Fig 2)

Mechanical Engineering drawings


Some examples of mechanical engineering drawings are part and assembly drawings, riveted joints, welded joints, fabrication drawings, pneumatics and hydraulics drawings, pipeline diagrams, keys coupling drawings etc. (Fig 3&4)

Electrical engineering drawing



Wiring diagrams of home and industries, circuit diagrams, electrical installation drawings etc.

Example


The voltage supply to a filament lamp is 10.8V. The voltage should be 12V. (Fig 5)



Mechanical Engineering Drawings (Fig 3&4)




Electrical Engineering Drawing (Fig 5)




Electronics Engineering Drawing









Audio amplifier (Fig 6)



Civil Engineering Drawing (Fig 7)



Conventions

| TYPE | CONVENTION | MATERIALS |
|----------------------------------|---|--|
| Metals |  | Steel, Cast Iron, Copper and its Alloys, Aluminium and its alloy, etc |
| |  | Lead, Zinc, Tin, White-metal, etc. |
| Glass |  | Glass |
| Packing and Insulating materials |  | Porcelain, Stoneware, Marble, Slate etc |
| |  | Asbestos, Fibre, Felt, Synthetic resin products, Paper, Cork, Linoleum, Rubber, Leather, Wax, insulating & Filling Materials etc |
| Liquid |  | Water, Oil, Petrol, Kerosene etc |
| Wood |  | Wood, Plywood etc |
| Concrete |  | Concrete |

Sizes and layout of drawing sheets

Size of drawing sheets (in mm): While being worked on or handled, the drawing sheets are prone to tear along the edges. So slightly larger (untrimmed) sheets are preferred. They are trimmed afterwards. IS:10811:1983 lays down such as designation of preferred trimmed and untrimmed sizes.

Designation of sheets: The drawing sheets are designated by symbols such as A0, A1, A2, A3, A4 and A5. A0 being the largest and A5 is smallest. Table 1 below gives the length and breadth of the above sizes of sheets. (Trimmed and untrimmed)

The relationship between two sides is same as that between a side of a square and its diagonal.

TABLE 1

| Designation | Trimmed size | Untrimmed size |
|-------------|--------------|----------------|
| A0 | 841 x 1189 | 880 x 1230 |
| A1 | 594 x 841 | 625 x 880 |
| A2 | 420 x 594 | 450 x 625 |
| A3 | 297 x 420 | 330 x 450 |
| A4 | 210 x 297 | 240 x 330 |
| A5 | 148 x 210 | 165 x 240 |

Special elongated series increasing its widths, double, treble etc. are denoted as follows A3 x 3, A3 x 4, A4 x 3, A4 x 4, A4 x 5. Please refer Table 2.

TABLE 2

Special elongated series

| Designation | Size |
|-------------|------------|
| A3 x 3 | 420 x 891 |
| A3 x 4 | 420 x 1189 |
| A4 x 3 | 297 x 630 |
| A4 x 4 | 297 x 841 |
| A4 x 5 | 297 x 1051 |



Fig 1 & 2 shows how the sheet sizes are formed by halving/doubling and similarity of format.

White drawing papers that do not turn yellow on exposure to air are used for finished drawings, maps, charts and drawings for photographic reproductions.

For pencil layouts and working drawings, cream-coloured papers are best suited.

Quality drawing paper: The drawing papers should have sufficient teeth or grain to take the pencil lines and withstand repeated erasing.


To get uniform lines, backing paper is to be placed on the drawing board before fixing drawing/tracing paper. Before starting the drawing, the layout should be drawn. (Ref: IS:10711)



The following is the method of folding printed drawing sheets as recommended by BIS. (Fig 3)

Method of folding of printed drawing sheets as per BIS SP: 46-2003

When drawings sheets are in more numbers, they have to be folded and kept in order to save the trace required for preserving them (Fig 4).




EDNSM110311

EDNSM110312

EDNSM110314

Method of folding printed drawing sheets (Fig 3)




EDNWL110313

METHOD OF FOLDING OF PRINTED DRAWING SHEETS


Title block, its position and content

Layout of drawing sheet:


As a standard practice sufficient margins are to be provided on all sides of the drawing sheet. The drawing sheet should have drawing space and title space. A typical layout of a drawing sheet is shown in the (Fig 1 & 2).




Title Block - 1




Title Block - 2



Title Block - 3



Title Block - Position and content - 1




Title Block - Position and content - 2

Fig 6

DO NOT SCALE

| REVISION | | | |
|----------|-----------------|----------|-------|
| SL.N | DESCRIPTION | DATE | APPX |
| A | M12 WAS ½ WHIT. | 14.12.18 | A.W.D |

| 4 | | | |
|-----------------|-------------|------------|---|
| 3 | | | |
| 2 | | | |
| 1 | A7325 | VALVE BODY | 1 |
| DRG OR PART NO. | DESCRIPTION | QTY. | |

| | | | | | |
|--|---|-----|-----------------|-----|--------------------|
| UNLES OTHERWISE STATED ALL DIMENSIONS IN MILLIMETRES. TOLERANCES LINEAR: ANGULAR: |  | DRN | 1:1:78 | JKL | (NAME OD THE FIRM) |
| | | CKD | 2:1:78 | MLN | |
| APPD | 5:1:78 | AWB | (TITLE OF DRW.) | | |
| ISSUED | 4:2:78 | PFP | | | |
| DRAFTING STANDARD AS 1100 | MATERIAL : CAST STEEL | | | | SIZE A3 |
| | FINISH AS MACHINED | | | | DRG NO A24641 |
| | | | | | SCALE 1:2 |
| | | | | | SHEET 1 OF 1 |

U

EDNSM110416

Item Reference on Drawing Sheet

| 05 | TIGHTENING PIN | 01 | MILD STEEL | |
|--------------------------|---------------------|----------|------------|---------|
| 04 | WORKPIECE | 01 | ANY MATL. | |
| 03 | SCREW ROD | 01 | STD. | |
| 02 | "U" CLAMP | 01 | CAST IRON | |
| 01 | "V" BLOCK | 01 | CAST IRON | |
| PART NO | DESCRIPTION OF ITEM | QTY/ASSY | MATERIAL | REMARKS |
| BILL OF MATERIALS | | | | |

The drawing sheet on which the drawings to be prepared should be prepared first by following the procedure given below:


- 1 Take A4/A3 drawing sheet.
- 2 Mark the borders and draw the title block as mentioned.

- 3 Follow the same procedure for A3 drawing sheet where the title block is to be drawn right side bottom corner and the border dimensions remain same.
- 4 Title block to be drawn whenever the title of the drawing changes. Eg. for the geometrical construction chapter the title block may be drawn in the first sheet only where as on the remaining sheets borders to be drawn before they are used for preparing drawings.

Drawing instruments

The following are the commonly used equipment in a drawing office.

Drawing board (Fig 1): Drawing board is one of the main item of equipment for Draughtsman. It is used for supporting the drawing paper/tracing paper for making drawings. It is made of well-seasoned wood strips of about 25 mm thick or masonite, free from knots and warping. It should be softer enough to allow insertion and removal of drawing pins. Two battens are fastened to the board by screws, in slotted joints. They prevent warping and at the same time permit expansion and contraction of the strips due to the change of moisture in the atmosphere.



One of the shorter edges of the drawing board is provided with an "ebony edge" (hardwood) fitted perfectly straight.

Standard drawing boards are designated as follows as per IS:1444-1989.

| Sl. No. | Designation | Size (mm) |
|---------|-------------|------------------|
| 1 | D0 | 1500 x 1000 x 25 |
| 2 | D1 | 1000 x 700 x 25 |
| 3 | D2 | 700 x 500 x 15 |
| 4 | D3 | 500 x 350 x 15 |

The working edge (ebony) must be straight.

Now-a-days drawing boards are available with laminated surfaces. The flatness can be checked by placing a straight edge on its surface. If no light passes between them, the surface is perfectly flat.

'T' Square: It is of 'T' shape, made of well-seasoned wood. It has two parts., head/stock and blade. One of the edges of the blade is the working edge. The blade is screwed to this head such that the working edge is at a right angle to the head. (Fig 2a)


The standard 'T' square is designated as follows with dimensions shown in mm; as per IS:1360-1989.

| Sl. No. | Designation | Blade length |
|---------|-------------|--------------|
| 1 | T0 | 1500 |
| 2 | T1 | 1000 |
| 3 | T2 | 700 |
| 4 | T3 | 500 |


The 'T' square is used with its head against the ebony edge of the drawing board to draw horizontal lines, and parallel lines and to guide/hold the set squares, stencils etc.

Fig 2b shows how the 'T' square is used.

'T' square should never be used as a hammer or as a guide for trimming papers.



Drafting in the machine (Fig 3): It serves the functions of a Tee square, set square, protractor and scale. They come in different sizes and have a pattern called the 'Pantograph' type. It is fitted on the top left side, edge of the drafting board, mounted on an adjustable frame or table. It requires a large area of working place. The angle of the drafting board can be adjusted by the pedal operating system. There are two counterweights to balance the angular position of the board and the drafting head. It is more suitable for the production drawing office.






On the other end, a protractor head H with swivelling and locking arrangement is fitted with two scales at right angles.

The protractor head has a spring-loaded clutch relieving handle, which rotates and locks at 15° intervals automatically. For setting any angle other than multiples of 15°, the clutch spring is released and by rotating the centre knob, the zero line is set to the required angle and the friction clutch knob is tightened. It is capable of rotating 180°, thereby any angle can be set.


The scales are bevelled on both sides, graduates to 1:1 & 1:2. They can be reversed with the help of dovetail slide fitting.

There is a fine adjusting mechanism on the drafting head to set the scale parallel to the edge of the board. The scales also can be adjusted if there is an error in measuring 90° between them.


The mini drafter is an important device used for making drawing quickly & accurately. This instrument has the combination of T-square, set square, protractor and scales, it helps to draw the drawings at a faster rate. (Fig 4, 5 & 6)




Erasing shield: When, on a drawing, if a part of a line or some lines among many other lines needs to be erased or modified, in a normal way erasing will damage the other nearby lines. In such a situation an erasing shield is effectively useful. It is a thin metallic sheet having small openings of different sizes and shapes. A suitable opening is aligned to the line to be erased and the line is removed by the eraser. (Fig 7)



Set square (IS:1361-1988): Transparent celluloid/Plastic set squares are preferred and are commonly used rather than ebonite ones. They are two in number, each having one corner with 90°. The set square with 60° & 30° of 250 mm long and 45° of 200mm long is convenient for use. (Fig 8)




Scales: Scales are used to transfer and or measure the dimensions. They are made of wood, steel, ivory, celluloid or plastic, stainless steel scales are more durable. different types of scales used are shown in Fig 9. They are either flat, bevel-edged or triangular cross-sections. Scales of 15cm long, 2cm wide or 30cm long 3.5cm wide are in general use.



Protractor: A protractor is an instrument for measuring angles. It is semi-circular or circular and is made of a flat celluloid sheet.

The angles can be set or measured from both sides, aligning the reference line and point '0' with the corner point of the angle.



Figure 10 shows how to read or set the angle. A protractor can also be used to divide a circle or draw sectors.



French curves (Fig 11)

These are made in many different shapes, normally come in sets of 6, 12, 16 etc. French curves are best suited to draw smooth curves/arcs (which cannot be drawn by a compass) with ease. To draw a smooth curve using a french curve first set it by trial against a part of the line to be drawn, then shift it to the next portions.


Fig 12 shows how to use the french curve and draw smooth curves. They are made of transparent celluloid (no bevel edge).



An instrument box contains the following: (Fig 13a to h)



- Large compass (with attachment facility) (a)
- Large divider (b)
- Bow compasses(pencil/ink), bow divider (c)
- Lengthening bar (d)
- Pen point for attachment (e)
- Screwdriver (f)
- Lead case (g)
- Liner (h)

Large compass (Fig 14): It has a knee joint in one leg that permits the insertion of a pen or pencil point or attaching a lengthening bar with a pen or pencil point attached to it. It is used for drawing large circles/arcs and also for taking large measurements.




As a rule, while drawing concentric circles, small circles should be drawn first before the centre hole gets worn.

Large divider: It is used to transfer dimensions and divide lines into several equal parts. Divider with adjustable joints is preferable rather than plain legs. (Fig 15)




Bow instruments: Bow pencil and bow pen compass are used for drawing circles of approximately 25 mm radius. A bow divider is used for marking or dividing smaller spaces. There are two types (i) Integral legs with spring action (ii) two legs are held with a curved spring on top with a handle on it.


Fig 16 shows different types of bow instruments. Adjustments should be made with the thumb and middle finger.




Drop spring bow pencil and pen (Fig 17): Drop spring bow pencil and pen are designed for drawing multiple identical small circles. Example: rivet holes, drilled/reamed holes. The central pin is made to move freely up and down through the tube attached to the pen or pencil unit.



Inking pen or liner or ruling pen (Fig 18): It is used to ink the straight lines drawn with the instruments but never for freehand lines or lettering.




Lengthening bar (Fig 19): To draw larger circles, it is fitted to the compass. The pencil point or pen point is inserted into its end.




Replaceable spare pencils, pens and needle points for the compass are available in the instrument box.


Screwdriver (Fig 20): Used for adjusting the screws of the instruments.




Lead case (Fig 21): Lead case is the box for holding the pencil leads.



Pin, Clip, Cello tape: Drawing sheet should be fastened onto the drawing board firmly temporarily so that it does not shake during preparing the drawing. For this purpose, the pins, clips and cello tapes are used (Fig 22)



Pencils, Grade and Selection (Fig 23)



Grades of pencils: Pencils are graded according to the hardness or softness of the lead.

The hardest pencil is 9H grade and the softest pencil is 7B grade. The selection of the grade of pencils depends on the type of line work required and the paper on which it is used.

Softer lead pencils are used to produce thicker and darker line work, but they wear out quickly. Medium grades of H and 2H are used for general line work as well as for lettering.

Selection of pencils: Pencil grades vary from one brand to another brand. Select the grades of the pencil depending upon the type of line work. For construction lines, you can choose 2H or 3H, for lettering and object lines grade H pencils. In general H, HB and 2H are used.

H - medium-hard

HB - medium-soft

2H - hard

Now-a-days automatic (Mechanical) pencils or clutch pencils are available in different sizes (lead dia. 0.3, 0.5, 0.7 or 0.9). Leads can be replaced as per the required grade of hardness. They produce lines of uniform width without sharpening.











Lines - Types and applications in drawing

Drawings are made up of different types of lines. Just a language with alphabet and grammar.

Lines of different thicknesses and features are used for specific use. (Fig 1 and 2)

Technical drawings are drawn with different types of lines. By proper choice and application of lines, product features can be correctly defined in a drawing. Different types of lines recommended for specific applications are given in Table 1.

Table 1
Types of lines and their application

| Lines | Description | General applications See figure and other relevant figure |
|--|--|--|
| Fig 1 | Continuous thick | A1 Visible outlines A2 Visible edges |
| A  0.5 | Continuous thin (straight) | B1 Imaginary lines of intersection B2 Dimension lines B3 projection lines or extension line B4 Leader lines B5 Hatching B6 Outlines of revolved sections in place B7 Short centre lines B8 Thread line B9 Diagonal line C1 Limits of partial or interrupted views & sections, if the limit is not a chain thin D1 Line (See figures) |
| B  0.2 | | |
| C  0.2 | Continuous thin free hand | |
| D  0.2 | Continuous thin (Straight) with zig-zags | |
| E  0.3 | Dashed thick | |
| F  0.2 | Dashed thin | |
| G  0.2 | Chain thin | |
| H  0.3 | Chain thin, thick at ends & changes of direction | |
| J  0.5 | Chain thick | |
| K  0.2 | Chain thin double-dashed | K1 Outlines of adjacent parts K2 Alternative and extreme positions of movable parts K3 Centroidal lines K4 Initial outlines prior to forming K5 Parts situated in front of the cutting plane |

- 1 This type of line is suited for production of drawings by machines.
- 2 Although two alternatives are available, it is recommended that on any one drawing, only one type of line be used.

In the above range, for craftsmen, 0.5 is preferred. Table 2 shows the 0.5 line range and other lines under this range.

The numbers on the right side of the lines refer to the line thickness in mm.


Table 2

| Fig 2 | | |
|-------|--|-----|
| A | | 0.5 |
| B | | 0.2 |
| C | | 0.2 |
| D | | 0.2 |
| E | | 0.3 |
| F | | 0.2 |
| G | | 0.2 |
| H | | 0.3 |
| J | | 0.5 |
| K | | 0.2 |


All the views of a component drawn to one particular scale should have the same range of line thickness.

Types of lines: Ten types of lines are used in general engineering drawing as per IS:10714-1983. Which first four types of lines are continuous lines of both thick and thin. (Type A to D)

A continuous thick line (A-type) is used for drawing visible outlines (A1) and visible edges (A2). (Fig 3) These lines are also called object lines




Continuous thin lines (B type): Continues thin lines are used for many applications as stated in Table 1. A few applications of B types of lines are shown in Fig 4.




A leader line - B4 (Fig 4): A leader line is a line referring to a feature (dimension, object, outline etc). A leader line should terminate.

- with a dot
- with an arrow head
- without a dot or arrow head (Fig 5)




Hatching lines (B5): Hatching lines are the lines inclined parallel lines. The minimum space between these lines should be more than twice the thickness of the heaviest line in the drawing. It is recommended that these spacings should never be less than 0.7 mm. (Fig 4)


For showing the limits of partial or interrupted views and sections continuous thin freehand lines (C1) or continuous thin straight lines with zig-zag (D1) are used. (Fig 6)





Lines of type E to K in Table 1 are of the non-continuous type. Some of these are thin and some are thick. For hidden lines both thick and thin dashes (E & F type) are available, it is recommended that on anyone drawing, only one type of (Thick or thin) line be used. (Fig 7)




Chain lines (Thin): Chain lines are used for drawing centre lines of circles, cylinders etc. Same lines are also used to show the axis of symmetry in symmetrical objects. The line of symmetry is identified at its ends by two thin short parallel lines drawn at right angles to it. (Fig 8)



Another method of representing symmetrical shape is to extend the object lines beyond the axis of the symmetry. (Fig 9) In this case, the short parallel lines described above are omitted. The same lines are also used to show the repetitions of features of a component. (Fig 10)





For drawing a sectional view, the plane of cutting is to be shown in another view. The cutting plane (H1) in Table 1 is drawn with a thin chain, thick at the ends and also at the places of direction change. (Figs 11 & 12)




If thick chain lines (J1) in table 1 are drawn on a surface, it indicates some special treatment/application on that surface. (Fig 13)

Chain thin double dashed (K) lines are applied for the following:


- K1 - Outlines of adjacent parts (Fig 13)
- K2 - Alternative and extreme positions of moving parts. (Fig 13)




K3 - Centroidal lines (Fig 14)



K4 - Initial outlines before forming (Fig 15)




K5 - Parts situated in front of the cutting plane (Fig 16)




Lines - Drawing lines of a given length (straight, curved), drawing parallel lines, perpendicular lines and methods of division of line segment

There are a lot of ways to define straight and curved lines; the most elaborate way to define them is the following:






- A straight line is a succession of points that are aligned in the same direction. Or in other words, to go from one point to another, we never change direction. (Fig 17)




- On the contrary, the points of a curved line do change direction from one point to the next. (Fig 18)




- If there aren't any obstacles, there are plenty of ways to do this...for example: (Fig 19 to 23)




Tangent line (Fig 24)



4 Easy ways to draw curved line (Fig 25)



Drawing curved dashed line (Fig 26)



Exercise 1

How to draw six horizontal parallel lines of 50 mm long with 10 mm intervals (Fig 1).



Use a sharpened conical point pencil.


Keep the pencil slightly inclined towards the direction of the movement.

While drawing rotates the pencil to keep the constant thickness.

Maintain uniform pressure on the lead of the pencil.

Exercise 2


How to draw six vertical parallel lines of 50 mm length with 10 mm intervals (Fig 2).



Draw the vertical lines from bottom to top.

Exercise 3

How to draw 45° inclined lines (Fig 3).




Draw lines from bottom to top.

Sketch by free hand


Sketch the following practice No.1 to 3 in A3/A4 sheets.

Practice


1 To draw horizontal thick and thin lines. (Fig 1)



2 To draw vertical thick and thin lines. (Fig 2)




3 Sketch the inclined lines as shown in figure with thick and thin lines. (Fig 3)



Types of lines


A point represents a location in space, having no width or height. It is represented by drawing the intersection of lines or a dot. (Fig 4)




A line is the path of a point when it moves. It has no thickness and is of two types:

- i Straight line and ii Curved line


Straight-line: It is the path of a point when it is moving in a particular direction. It has only length and no width. (Fig 5) Also, a straight line is the shortest distance between two points. Straight lines, depending on their orientation are classified as Horizontal, Vertical Inclined or Oblique lines.




Horizontal line (Fig 6): Horizontal lines are those which are parallel to a horizontal plane. An example of the horizontal plane is the surface of still water. (Fig 6)




Vertical line (Fig 7a): Lines that are perpendicular to horizontal lines are called vertical lines. It can be treated as a line along the plumb line of the plumb bob or parallel to a plumb line. (Fig 7b)




Inclined line or Oblique line: A straight line that is neither horizontal nor vertical is called an inclined line. (Fig 8)




Curved line: It is the path of a point that always changes its direction. Examples of curved lines are shown in (Fig 9).



Parallel lines: They are the lines with the same distance between them. They may be straight lines or curved lines. Parallel lines do not meet when extended. (Fig 10)



Perpendicular lines: When two lines meet at 90°, the two lines are said to be perpendicular to each other. One of the lines is called a reference line. (Fig 11)




Free hand drawing of - Geometrical figures and block with dimension

Freehand sketching: Apart from making drawing using instruments, often craftsmen will be required to make drawings with their free hand.


Freehand sketching is the easiest method to express the shape of a piece part or a component by an engineer or craftsman.

Freehand sketches are not usually made to scale. However, they should be as nearly to the proportions as possible.


Cube (Fig 1)




Square block (Fig 2)




Rectangular block (Fig 3)




Cube block (Fig 4)



Cylinder (Fig 5)




Materials for free hand sketching: A4 size sheet (preferably a pad instead of loose papers) pencils of soft grade. Example H, HB, and a good quality eraser are the only materials required. For drawing different darkness, the pencil points should be sharpened to a conical shape. Fig 6 shows some free hand sketches of different types of views.



Procedure

Freehand drawing of solid figures, cubes, cuboids, cone, prism, pyramid, frustum of a cone with dimensions


Cube (Fig 1)



- Draw squares of a, b, c and d.
- Draw 30° from points b, c and d for the length of 25mm.
- Mark point g from b, f from c and e from d as shown in the figure.
- Joint all points.

Cuboid (Fig 2)


Draw the isometric drawing of a cuboid of base 60 mm x 40 mm and the height of 20 mm. (Fig 2)




Draw the three isometric axes through the point 'A'.

- Mark AB = 60mm, AE = 40mm and AD = 20mm representing the three sides of cuboid.
- Draw two vertical lines EF and BC parallel to AD from points E and B respectively.
- Similarly, draw two more lines parallel to AB and AE to mark G's interesting point from F and C.
- Draw lines parallel to DC and FG. Draw lines parallel to DF and GC.
- Join all the points.


Cylinder (Fig 3)




Rectangular prism (Fig 4)




Square Prism (Fig 5)




Triangular Prism (Fig 6)




Pentagonal prism (Fig 7)



Hexagonal prism (Fig 8)



Cone: When a right-angled triangle revolves about one of its sides forming the right angle, a cone is generated. Cone forming has a circular face and a slant curved surface. (Fig 9)



Pyramids: Pyramids are polyhedron solids having a base surface whose shape may be triangular, square or polygon and as many slant triangular faces as there are sides in the base. All the slant triangular faces join at a common point called APEX.

Similar to prisms, pyramids also are known by the shape of their base viz triangular, square, rectangular, pentagonal, hexagonal etc. The imaginary line joining the centre of the base to the apex is called the AXIS.

Fig 10 shows some pyramids and their views.

When a semi-circle revolves about its diameter a sphere is generated. A sphere has no flat surface. (Fig 11D)

Frustums: Pyramid/cone is cut parallel to the base and the top portion is removed. The remaining bottom portion is called the frustum of a pyramid/cone.

If the cutting plane is at an angle to the axis/base, the pyramids or cones are called "Truncated pyramids or cones".






Fig 12 shows frustums and truncated pyramids.

All items we use are solids. Their shapes may confirm individual geometrical solids like prisms, cones or other combinations.



Free hand drawing of - Transferring measurement from the given object to the free hand sketches







Fig 3

(a)




(b)




EDNSM120813

Fig 4

(a)




(b)




EDNSM120814

Fig 5

(a)



(b)



EDNSM120815








Fig 9

(a)




(b)




EDNS/M120819

Fig 10

(a)



(b)




EDNS/M12081A

Free hand drawing of hand tools and measuring tools


Hand Tools

Files (Fig 1)


- a Curved cut file
- b Rasp cut file
- c Single cut file
- d Double cut file




Scriber (Fig 2)




Divider (Fig 3)




Outside caliper (Fig 4)




Inside caliper (Fig 5)




Hacksaw (Fig 6)




Ball pein hammer (Fig 7)




Chisel (Fig 8)




Bench vice (Fig 9)



Cutting plier (Fig 10)



Open end spanner (Fig 11)



EDNSM120916

EDNSM120917

EDNSM120918


EDNF120919

EDNSM120914


EDNSM120915

Measuring Tools


Steel rule (Fig 12)




Try square (Fig 13)




Rawhide mallet (Fig 14)




Setting hammer (Fig 15)




Riveting hammer (Fig 16)




Aviation shear (Fig 17)




Creasing hammer (Fig 18)




Hollowing hammer (Fig 19)




Bullet hammer (Fig 20)




Planishing hammer (Fig 21)




Bench shear (Fig 22)




Straight snip (Fig 23)




Bend snip (Fig 24)




Hawk-billed shear (Fig 25)




Double-cutting shear (Fig 26)




Round bottom stake (Fig 27)




Half moon stake (Fig 28)




Beak or bickiron (Fig 29)




Creasing iron (Fig 30)




Tinman's horse (Fig 31)




Heads (Fig 32)




Tinman's anvil (Fig 33)




Penning hammer (Fig 34)




Universal stake holder (Fig 35)




Square edge (Fig 36)




Hand seamer (Fig 37)




Hollow punch (Fig 38)




Folding bars (Fig 39)




Revolving bench plate (Fig 40)




Blind rivetting equipment (Fig 41)




Solid punch (Fig 42)




Iron hand punch (Fig 43)




Hand riveter (Fig 44)



Size of groove & seam (Fig 45)




Tinner's hand punch (Fig 46)




Drawing of angle & triangle

Angles: Angle is the inclination between two straight lines meeting at a point or meeting when extended. AB and BC are two straight lines meeting at B. The inclination between them is called an angle. The angle is expressed in degrees or radians.


Concept of a degree: When the circumference of a circle is divided into 360 equal parts and radial lines are drawn through these points, the inclination between the two adjacent radial lines is defined as one degree. Thus a circle is said to contain 360°. (Fig 1)




Acute angle: An angle that is less than 90° is called an acute angle. (Fig 2)




Right angle: The angle between a reference line and a perpendicular line is called a right angle. (Fig 3)




Obtuse angle: This refers to an angle between 90° and 180°. (Fig 4)




Straight angle: This refers to an angle of 180°. This is also called the angle of a straight line. (Fig 5)




Reflex angle: It is the angle that is more than 180°, but less than 360°. (Fig 6)




Adjacent angles: These are the angles lying on either side of a line. (Fig 7)



Complementary angles: When the sum of the two angles is equal to 90°, angle POQ + angle QOR = 90° angle POQ and angle QOR are complementary angles to each other. (Fig 8)



Supplementary angle: When the sum of the two adjacent angles is equal to 180°, for example, angle SOT + angle TOY = 180°, angle SOT and angle TOY are supplementary angles to each other. (Fig 9)



Triangle - different types


Triangle is a closed plane figure having three sides and three angles. The sum of the three angles always equals to 180° .

To define a triangle, we need to have a minimum of three measurements as follows:


- 3 sides or
- 2 sides and one angle or
- 2 angles and one side

Types of triangles


1 Equilateral triangle is a triangle having all the three sides equal. Also all the three angles are equal (60°). (Fig 1)



2 Isosceles triangle has two of its sides equal. The angles opposite the two equal sides are also equal. (Fig 2)



3 Scalene triangle has all three sides unequal in length. All three angles are also unequal. (Fig 3)






4 A right-angled triangle is one in which one of the angles is equal to 90° (Right angle). The side opposite the right angle is called the hypotenuse. (Fig 4)

5 An Acute angled triangle is one in which all the three angles are less than 90° . (Fig 5)

6 Obtuse angled triangle has one of the angles more than 90° . (Fig 6)

The sum of the three angles in any triangle is equal to 180° .


The sum of any two sides is more than the third side.



Procedure to draw the triangle


1 Equilateral triangle (Fig 1) $AB = BC = CA = 35$ mm.

- Draw a line and mark AB 35 mm side of the triangle.
- Draw radius from centre A and B, arcs cutting mark at C (Fig 1).
- Join CA and CB.
- ABC is a required triangle.




2 Isosceles triangle: $AB = AC = 60$ mm & $\angle BAC = 40^\circ$.

- Draw the side AB equal to 60 mm. 'A' as the centre, draw an arc of radius AB.
- Draw a line AC at 40° to AB.
- Join BC to form the triangle ABC. (Fig 2)




Exercise

- 1 **Scalene triangle: $AB = 30$ mm, $AC = 55$ mm & $BC = 35$ mm. (Fig 1)**




- 2 **Scalene triangle: $AB = 70$ mm. (Fig 2)**


$\angle ABC = 40^\circ$ & $\angle BAC = 110^\circ$




- 3 **Right angled triangle: $AB = 60$ mm, $BC = 45$ mm. (Fig 3)**




- 4 **Draw a triangle when one side and 2 angles being given in Fig 4.**



- 5 **Draw a right angled triangle when the base and hypotenuse being given in Fig 5.**



- 6 **Draw a triangle with the altitude and two sides being given in Fig 6.**



Drawing of circle

Circle: Circle is a plane figure bounded by a curve, formed by the locus of a point which moves so that it is always at a fixed distance from a stationary point the "Centre".

Radius: The distance from the centre to any point on the circle is called the "Radius".

Diameter: The length of a straight line between two points on the curve, passing through the centre is called the "Diameter". (D: Dia or d) It is twice the radius.

Circumference: It is the linear length of the entire curve, equal to πD .

Arc: A part of the circle between any two points on the circumference or periphery is called an 'Arc'.

Chord: A straight line joining the ends of an arc is called the chord. (Longest chord of the circle is the diameter)

Segment: A part of the circle or area bound by the arc and chord is the segment of the circle.


Sector: It is the part of a circle bounded by two radii (plural of radius) meeting at an angle and an arc.

Quadrant: Part of a circle with radii making 90° with each other is a quadrant (one-fourth of the circle).

Half of the circle is called a semi-circle.



Tangent: The tangent of a circle is a straight line just touching the circle at a point. It does not cut or pass through the circle when extended.

Fig 1 shows all the above elements.



Concentric circles: When two or more circles (drawn) have a common centre, they are called concentric circles. Ball-bearing is the best example of concentric circles. (Fig 2)


Eccentric circles: Circles within a circle but with different centres are called eccentric circles. (Fig 3)



Circle and Arcs


Exercise

1 Draw a tangent to a given circle of ϕ 50 mm at any point 'P' on it. (Fig 1)




2 Draw a loop of 3 circles pattern. (Fig 2)


Draw any line MN and mark points A,B and C. So that AB = 20 mm and BC = 25 mm.




3 3 Draw three circles tangential to each other if centres A, B & C are given. (Fig 3)



4 Draw external tangents to circles of dia 40 and 30 and centre distance 60 mm. (Fig 4)




5 Draw internal tangents to circles of the same diameter 40 each and a centre distance of 60 mm. (Fig 5)



Drawing of square, rectangle and parallelogram

A quadrilateral is a plane figure bounded by four sides and four angles. The sum of the four angles in a quadrilateral is equal to 360° . The side joining opposite corners is called diagonal. To construct a quadrilateral out of four sides, four angles and two diagonals a minimum of five dimensions are required of which two must be sides. Quadrilaterals are also referred as Trapezium. (Fig 1)




Types of quadrilaterals (Fig 1)

- Square
- Rectangle
- Rhomboid/Parallelogram


Square: In a square all the four sides are equal and its four angles are at right angles. The two diagonals are equal and perpendicular to each other.

Rectangle (Fig 2): In a rectangle, opposite sides are equal and parallel and all four angles are right angles.

Fig 2 shows a rectangle ABCD, Sides AB = DC and BC = AD. Diagonals AC and BD are equal. Diagonals are not bisected at right angles.




Rhomboid/Parallelogram (Fig 3): In a parallelogram, opposite sides are equal and parallel. Opposite angles are also equal. Diagonals are not equal but bisect each other.




Procedure to draw the square, rectangle and parallelogram

Square


1 **1st method (Fig 1):** A square of side 50 mm by erecting perpendicular.




2 **2nd method (Fig 2):** A square of side 60 mm using 45° setsquare and compass.



3 **3rd method (Fig 3):** A square of side 60 mm long by erecting perpendicular and also using 45° setsquare.




4 Square having diagonal 60 mm (Fig 4)



5 Rectangle (Fig 5)


Side AB = 75 mm, side AD = 45 mm using setsquare and compass.



6 Rectangle - Diagonal - 60 mm and one side 20 mm 1st method (Fig 6a)

2nd method (Fig 6b)


ADBC is the required rectangle of side 20 mm and diagonal 60 mm.



7 Parallelogram (Fig 7)

Sides = 75 mm and 40 mm


Angle between them: 50°



8 Parallelogram (Fig 8)


Parallelogram - Side AB = 60 mm

Diagonal AC = 90 mm $\angle ABC = 120^\circ$



9 Parallelogram (Fig 9)

Sides AB = 55 mm, BC = 40 mm and vertical height = 30 mm.




Drawing of ellipse & parabola

Ellipse

1 Construct an ellipse by concentric circle method. Major axis 80 mm. Minor axis 40 mm. (Fig 1)


- Draw the major axis AB (80 mm) and minor axis CD (40 mm), bisecting at right angle at O.
- 'O' as centre OA and OC as radius, draw two concentric circles.
- Draw a number of radial lines through 'O' (say 12) cutting the two circles.
- Mark the points on the outer circle as a,b,c.
- Similarly mark the corresponding intersecting points on inner circle as a',b',c'.
- From points such as a,b,c... draw lines parallel to minor axis.
- From points such as a',b',c'.... draw lines parallel to the major axis to intersect with the corresponding vertical lines at points P₁, P₂,P₃.... etc.
- Join all these points with a smooth curve by free hand or using "french curve" and form the ellipse.
- To find the 'Foci' - with half the major axis (a) as radius and with 'C' on the minor axis as centre, draw an arc cutting the major axis, at two points, mark them as F₁,F₂ the focus points of the ellipse.




2 Construct an ellipse by four centre method - Major axis = 80 mm and Minor axis = 40 mm - Type A. (Fig 2)

- Draw the major axis A₁A₂ and minor axis B₁B₂.
- Set off B₁M₂ and B₂M₄ equals to A₁B₁.
- Join A₁B₁ and set off B₁B₃ equal to a-b (a = OA₁, b = OB₁)
- Draw a bisector on A₁B₃ which intersects A₁A₂ at M₁.

- Similarly obtain M₃. M₂ & M₄ as centres and B₁M₂ as radius, draw arcs P₁P₂ & P₃P₄.
- M₁M₃ as centres and M₁P₁ as radius, draw arcs P₁P₃ & P₂P₄ and complete the ellipse.



3 Construct an ellipse by four centre method - Major axis = 80 mm and Minor axis = 40 mm - Type B. (Fig 3)



- Draw the rectangle EFGH (80 x 40) and draw AB & CD represent major and minor axis.
- Join EC
- Bisect AE and mark P the mid-point.
- Join DP meeting EC at K.
- Draw perpendicular bisectors of KD and extend DC and locate point 'S'.
- 'S' as centre SD as radius draw the arc KD.
- Similarly get the point 'R'.


- Join AK and draw perpendicular bisector on it, and meet AB at f_1 .
- f_1 as centre, Af_1 as radius, draw an arc KK' .
- Mark centre f_2 so that $Bf_2 = Af_1$.
- Now R, S, F_1 & F_2 are the four centres of the ellipse.

Similar to the procedure followed for drawing curves KD and KK_1 and complete the ellipse.

Follow the procedures given below and construct parabolic curves in the work book.

4 Parabola: It is one of the conic sections.

When the cutting plane is parallel to the generators (slant line) of the cone, (and inclined to the axis) the section obtained is called "Parabola". (Fig 4)



Properties: Parabola is defined as the locus of a point which moves so that the ratio of its distance from a fixed point F (called the focus) and a directrix bears a constant and equal to 1 (Unity).

In other words if the perpendicular distance of any point on the curve from a fixed line called directrix is equal to its distance from focus, the curve is called "Parabola". (Fig 5)

Elements of Parabola

Axis: It is a line (XX') perpendicular to the directrix and passing through the focus.


Vertex (V): It is the mid point of the perpendicular line drawn from focus to directrix.

Ordinate: Perpendicular distance of any point P on the curve to the axis line PQ.

Double ordinate: When the ordinate is extended to meet the curve on the other side. Crossing the axis, it is twice the ordinate line P-Q-P' is the double ordinate.

Latus rectum: The double ordinate which passes through the 'Focus' is called latus rectum. (LFL')

5 Abscissa: The distance along the axis XX' from vertex (V) and a point through which the double ordinate passes is called the "Abcissa" VQ is the abscissa corresponding to the ordinate PQ (Fig 5).



Tangent and normal for the point T

- Draw TS perpendicular to directrix
- Draw TF
- Bisect angle STF, it will be tangential to parabola at P.
- Draw TN perpendicular to tangent will be normal at P.

A parabola can be constructed by any one of the following methods:

- ordinate method
- rectangle method
- tangent method
- parallelogram method
- offset method

Practical application: Search lights, reflecting surfaces for light and sound, bridge arches, wall brackets and largely used in graphic methods for determining the stress upon beams and girders etc.


6 Parabola

Construct a Parabola from a given focus is at 50 mm from the directrix. (Fig 6) - Ordinate method.

- Draw a vertical line D-D¹ the directrix.
- Draw horizontal line XX¹, the axis through any point X on the directrix.
- Mark the focus 'F' on XX¹ = 50 mm from X (on the directrix).
- Mark the mid point of XF, as V.


- Mark a number of points from V towards right side on the axis as 1,2,3,4.....
- Draw vertical lines through these points as shown, forming double ordinates.
- Point 'F' as centre, X-1 as radius, draw arcs on the co-ordinates (vertical lines) passing through 1, mark points P_1 & P_1' .
- X-2 as radius, F as centre, draw arcs on the 2nd ordinate, mark P_2 & P_2' .
- Similarly get point $P_3, P_4 \dots P_3', P_4'$ etc. on the axis as above.
- Join all the points with a smooth curve, by free hand and form the parabola curve.

- Mark the intersecting points P_1, P_2, P_3, P_4 on either side of axis.
- Form the parabola by joining the points BEC and intersecting with a smooth curve, passing through $P_1, P_2 \dots$




7 Construct a Parabola given the base and axis of a rectangle; base 80 mm, axis 25 mm - Rectangle method. (Fig 7)

- Draw a rectangle ABCD of sides 80 mm & 25 mm.
- Mark centre points of AD and BC, as E and F, join EF.
- Divide AB & CD and into any number of equal parts say 5. Also divide AE and ED into the same number of equal parts and number them as shown.
- From point E on AD, draw lines to the divisions on AB & CD.
- From the points on AED, draw parallel lines to EF.



8 Parabolic curve of sides 80 and 60 making $60^\circ/120^\circ$ Parallelogram method. (Fig 8)


- Procedure is similar to the exercise (11) rectangle method of drawing a Parabolic curve.



9 Given the double ordinate, abscissa and distance between vertices (Fig 9)

- Draw a hyperbola with double ordinate 70 mm and abscissa 30 mm (rectangle method) and the transverse axis 70 mm.

- Draw the rectangle ABCD 70 x 30 mm.
- Mark the mid points V, X on AB and CD.
- Join VX and extend it outside to 'O' 35 mm (70/2) from V.
- Divide AD and BC into 4 equal parts. Mark them as 1,2,3,1',2',3'.
- Join these points to V by straight lines.
- Divide DX;XC into 4 equal parts, each mark them as a,b,c,c',b',a'.
- Join 'O' to these points by straight lines.
- Mark the intersecting points as P₁,P₂ etc as shown.
- Join V-D-C with a smooth curve through P₁,P₂,P₃ etc.



Drawing of lettering and numbering - Single stroke

Styles of lettering: Many styles of lettering are in use today. However, a few styles which are commonly used are shown in Fig 1.

Fig 1

| | |
|------------------------------------|--|
| ABCDEFGH abcdefgh | GOTHIC ALL LETTERS HAVING THE ELEMENTARY STROKES OF EVEN WIDTH ARE CLASSIFIED AS GOTHIC |
| ABCDEFGH abcdefgh | ROMAN ALL LETTERS HAVING THE ELEMENTARY STROKES "ACCENTED" OR CONSISTING OF HEAVY AND LIGHT LINES ARE CLASSIFIED AS ROMAN |
| <i>ABCDEFGH</i> <i>abcdefgh</i> | ITALIC ALL SLANTING LETTERS ARE CLASSIFIED AS ITALIC. THESE MAY BE FURTHER DESIGNATED AS ROMAN-ITALICS, GOTHIC-ITALICS, TEXT-ITALICS |
| ABCDEF abcd | TEXT THIS TERM INCLUDES ALL STYLES OF OLD ENGLISH, GERMAN TEXT, BRADELY TEXT OF OTHERS OF VARIOUS TRADE NAMES. TEXT STYLES ARE TOO ILLEGIBLE FOR COMMERCIAL PURPOSES |

EDNSM13121

Standard heights/Width: The standard heights recommended by BIS SP: 46-2003 are in the progressive ratio of "square root 2". They are namely 2.5 - 3.5 - 5 - 7 - 10 - 14 and 20 mm. The height of lower case letter (without tail or stem) are 2.5, 3.5, 5, 7, 10 and 14 mm.

There are two standard ratios for the line thickness "d". They are A & B. In A = line thickness (d) is h/14 and in B=line thickness (d) is h/10.

Lowercase means small letters, as opposed to capital letters. The word yes, is for example, is in **lowercase**, while the word YES is in **upper case**. For many programmes, this distinction is very important. Programmes that distinguish between **uppercase** and **lowercase** are said to be case sensitive

The width of different letters in terms of "d" is as follows:

Lettering A

| Width (W) | Capital letters | Width |
|-----------|-----------------------------|-------|
| 1 | I | 1d |
| 5 | J,L | 5d |
| 6 | C,E,F | 6d |
| 7 | B,D,G,H,K,N,O,P,R,S,T,U & Z | 7d |
| 8 | A,Q,V,X,Y | 8d |
| 9 | M | 9d |
| 12 | W | 12d |

Lower case letters and numerals

| Width (W) | Letters/Numerals | Width |
|-----------|---------------------------------|-------|
| 1 | i | 1d |
| 3 | j,l | 3d |
| 4 | f,t,l | 4d |
| 5 | c,r | 5d |
| 6 | a,b,d,e,g,h,k,n,o,p,q,s,u,v;3;5 | 6d |
| 7 | a,0 (zero), 2,4,6,7,0,8,9 | 7d |
| 9 | m | 9d |
| 10 | w | 10d |

The width of different letters in terms of stroke (line) is as follows:


Uppercase Lettering BIS SP: 46-2003

| Width (W) | Capital letters |
|-----------|-----------------------------|
| 1 | I |
| 4 | J |
| 5 | C,E,F,L |
| 6 | B,D,G,H,K,N,O,P,R,S,T,U & Z |
| 7 | A,M,Q,V,X,Y |
| 9 | W |

Lower case letters and numerals

| Width (W) | Letters/Numerals |
|-----------|--|
| 1 | i |
| 2 | l |
| 3 | j,l |
| 4 | c,f,r,t |
| 5 | a,b,d,e,g,h,k,n,o,,q,s,u,v,x,y,x 0,2,3,5 to 9 |
| 6 | 0,2,3,5 to 9 a,4 |


Spacing of letters: Recommended spacing between characters, a minimum spacing of baselines and minimum spacing between words as per BIS SP: 46-2003 are given below in Fig 2.



Lettering

Procedure

- 1 Print 10 mm single stroke capital letters and numerals in vertical style using either scale or set-square and by freehand. (Fig 1)



- Draw horizontal parallel lines (thin lines) of 10 mm distance.

10 mm distances denote the height of the letter.


- Mark the width of the letters recommended by BIS (IS:9609-1983)

The width of different letters in terms of 'd' is as follows: 'd' indicates stroke thickness i.e d: h/ 10.


| Width (W) | Capital letters |
|-----------|--|
| 1 | I |
| 4 | J |
| 5 | C, E, F, L |
| 6 | B, D, G, H, K, N, O, P, R, S, T, U & Z |
| 7 | A, M, Q, V, X, Y |
| 9 | W |

For curved letters use a smooth freehand curve.
Print straight line letters using either scale or set-squares.
To maintain the uniform thickness of the line, use a conical point soft grade pencil and avoid too much sharpness.
Guidelines of both top and bottom should always be drawn with a sharp pencil.

Numerals 2.1 (Fig 2)



- Follow the same procedure of letters.
- 'h' is height of numerals and 'd' is the stroke thickness.
- Width of numerals in terms of 'd' is as follows shown in square grid (Fig 3).



- 2 Print 10 mm single stroke capital letters and numerals in inclined style (Fig 4).



Practice the following lettering exercises in A3/A4 paper as per the given ratio

1 Single stroke inclined letters of ratio 7:6, 7:5, 7:4, 7:3, 7:1 (Fig 5)

Fig 5




SINGLE STROKE INCLINED LETTERS

EDNSM131425

2 Single stroke vertical letters of ratio 7:6, 7:5, 7.4, 7:3, 7:1 (Fig 6)

Fig 6



SINGLE STROKE VERTICAL LETTERS

EDNSM131426


Drawing of development of surfaces - Introduction

Surface development of prism, pyramid, cylinder projection & development, cone projection & development


Development of surface - Introduction

The surfaces may be classified as follows:


- Solids bounded by plane surfaces. Eg. cube, prism, pyramids etc. (Fig 1)



- Solids bounded by single curved surfaces. It can be unrolled to a plane. Eg. cylinder, cone etc. (Fig 2)




- Solids bounded by double curved surfaces. It is formed by revolving a curve about a straightline. Eg. sphere, paraboloid etc. (Fig 3)




Methods of development

Parallel line method (Fig 4i): This is method used for such of those object having parallel elements i.e developing prisms and single curved surfaces like cylinders, in which all the edges/generators of lateral surfaces are parallel to each other.

Radial line development (Fig 4ii): It is used for developing the surfaces of pyramids and also for single curved surfaces like cones, having its apex as centre and the slant edges or generators are taken as radius for drawing its development. Radial line development has the fold lines, coming from a point which is known as apex.




Intersection: We are more convinced with the lines of intersection formed when surfaces of two solid meet. Fig 5 shows the few examples of lines of intersection.




Intersection lines or just intersections are of great importance to both for making drawings for fabrication work.

When drawing the views of intersecting solids, lines of intersection will have to be drawn in order to complete the views. For example Fig 6 shows a solid when two cylinders meet at right angles. Without the line of intersection cd, the view is incomplete. To draw the intersection lines in its correct form, principle of projections have to be followed and this will involve extensive geometrical construction.



In fabrication work, especially in sheet metal fabrication accurate intersection lines are a must for drawing development.


For example, the development of the part 2 of Fig 6 is shown in Fig 7. The accuracy of the fabricated cylinder is much dependent on the accuracy of the curve cd. To plot the line cd, intersection line cd (Fig 6) has to be drawn accurately.



Depending on the nature of the meeting surfaces, intersection lines may be straight lines or curves. When both the mating surfaces are flat (plain) intersection will be straight lines (Fig 5c). If one or both the mating surfaces are curved, the intersection lines are curved. (Fig 5a, b & d)

To plot the points required for drawing the intersection curve we can use either the line method or cutting plane method.

Line method (Fig 8): Mark the points 1",2",3" on the circumference of the circle in the side view. (preferably symmetrical)



Project from side view and locate points P_2 ; P_1/P_3 in plan. Now these lines $P_3 - 3$, $P_1 - 1$ and $P_2 - 2$ are the true lengths of the generators or simply lines drawn from points 3, 1 and 2. These lines will also form the true lengths in the elevation.

Draw projectors of indefinite lengths from points 1",2" & 3" in the side view towards the elevation.


To fix the position of the above projectors, draw projectors vertically from points such as P_3/P_1 and P_2 to intersect with the corresponding lines in the elevation. Mark the intersecting points f_1', f_2', f_3' and draw the required curve.

Note: The above step was to simply transfer the true length of generators $P_1 - 1$, $P_2 - 2$ from plan to elevation.

Since we have drawn the projection of generators to get the points f_1', f_2', f_3' . This method is called generator method. This is also called as line method.

Cutting plane method (Fig 9): In cutting plane method, we assume that the cylinders are cut by a series of parallel cutting planes passing through such points as 3-3, 2-2 etc.

In figure 9, the cylinders are shown after they are cut by a plane passing through 3 - 3. The line $f_3 - 3$ is the same as the generating line $f_3' - 3''$ in the front view of figure and hence the rest of the procedure is same as that of line method.




Note: Though both line method and cutting plane method are appearing to be same, they are conceptually different. While any one method can be followed in many cases, but cutting plane method is more useful in solving cases in which none of the projections shows a line view of the surface of a solid.

Drawing of development of surfaces - Procedure

Practice of Surface development of prism, pyramid, cylinder projection & development, cone projection & development

Procedure

- 1 Draw the development of the surfaces of a cube of side 30 mm. (Fig 1)




- Draw the elevation and plan of the cube.
- From the front view stretch out (Project) the line AA & A'A' from points b₁ b' horizontally.
- Set off AB, BC, CD & DA equal to 30 mm each. (side of square)
- From C & D draw perpendiculars and mark off/CB' & DA' equals to 30 mm.
- Similarly erect perpendiculars from points C' & D' such that C'B₁ & D'A₁ equals to 30 mm.
- Darken the lines as shown in Fig 1 to get the required development of the cube.


- 2 Draw the development of the surface/a rectangular prism of size 40 mm x 20 mm and height 60 mm by parallel line method. (Fig 2)

- Draw a rectangle of length equals to the perimeter of the prism. Length = 2 (l + b) = 120 mm and height equals to the height of prism (60 mm).
- Mark AB; BC; CD and DA equals to 40, 20, 40 & 20 mm respectively.
- Draw perpendiculars from the points A,B,C,D and mark as A', B', C', D'.
- Draw a rectangle A'B'C'D' on A'B' of size 40x20 mm.

- Draw another rectangle CDA₁B₁ on CD of size to 40 x 20 mm, the end faces of the prism. Figure obtained is the development of the total prism.




- 3 Draw the development of the lateral surface of a open hexagonal prism of side 20 mm and height 60 mm. (Fig 3)



- Draw the elevation and plan of the hexagonal prism.
- Project A'A' & AA from the elevation C'C' , shall be equal to 6 x 20 = 120 mm.

- On A'A' set of A'1, 1-2, 2-3 etc. equal to the side of the hexagon.
- Through A', 1,2,3 etc, draw vertical lines meet at AA, 1',2',3' etc to complete the required lateral surface development of the hexagonal prism.


4 Draw the development of surfaces of the box. (Fig 4)



- Assume there is no slope surface and draw the development of cube of side 60 mm as given in Fig4.
- Draw lines PQ and RS in the surfaces 1 and 3 in the basic development equivalent the shape shown in the isometric view of the box.
- Similarly join a rectangle of size equal to the surface 7 shown in isometric view with line RS or PQ and complete the development after erasing the construction lines.


5 Draw the development of a rectangular prism as stated under and as shown in Figure. Prism is cut by a cutting plane at 30°, 30 mm from base on width side. (Fig 5)

- Draw the top view and front view of the rectangular prism.
- Mark 30 mm on front view from b'(c') to meet the line b'b', at m'
- At m' make an angle of 30° such that the cutting plane meet the line a'-a', at n'.
- Project b', m', n' horizontally and mark of AB = 35, BC = 15, CD = 35 & DA = 15 mm.
- From A,B,C,D,A of the front view, draw vertical lines and mark points 3, 4,1,2 & 3.
- Draw 1-4' and 2-3' perpendiculars to 1-2 equals to 15 mm and draw CB₁ & DA₁ perpendicular to CD and equals to 15 mm.
- Darken the lines throughout the development of the given prism.



6 Draw the development of the lateral surface of an open cylindrical drum of dia 30 mm and height is 60 mm. (Fig 6)

- Draw the plan and elevation of the drum as stated.
 - Project the front view and draw the side view to a length of circumference of the base of the cylinder.
- Circumference = $\pi D = \pi \times 30 \text{ mm} = 94.26$ or 94.3
- Rectangle thus formed is the development of cylinder.



7 Draw the development of a cone of base 60 mm and height 40 mm. (Fig 7)


- Draw the plan and elevation of the cone.
- Divide the plan circle into number of equal parts (say 12 parts) and mark.

Development is more accurate if the number of equal parts are more.

- Project these parts to the base of the cone.
- Join these points to the vertex of the cone.

- Locate O_1 vertex for the development of cone.
- Draw an arc from the vertex as centre and length of slope as radius.
- Set divider on the straight distance between two consecutive points on the plan.
- Transfer the distance along the arc as many times according to the divisions on the plan.
- Join points $1 O_1 1$ and complete the development.

This method is only an approximate method. The straight line distance taken is slightly smaller than the arc length. More accurate method is by calculating actual circumference and dividing it into number of segments.




9 Draw the development of the lateral surface of the cone as positioned. (Fig 8)

- Draw the views of the cone and cutting plane on it.
- Divide the base into any number of equal parts, say 12 and mark them.
- Project the points on to FV and join to the apex.
- Mark the points on the cutting plane and draw lines parallel to base, touching the generator at $1_1, 2_1, \dots, 7_1$. These are the true lengths from O' .
- Draw the sector with slope as radius.


$$\text{Sector angle } \theta = \frac{\text{radius of cone base circle}}{\text{Slant height length (s)}} \times 360^\circ$$

- Mark O_1 and set angle θ .
- Transfer the true lengths on the cone on to the sectors and join by smooth curve.

The area between this curve and the arc is the development of the lateral surface.




12 Draw the development of the lateral surface of the frustum of a square pyramid as positioned. (Fig 9a)



- Draw the front view and plan of the pyramid. (Fig 9b) None of lines in these views show the true length of slant edge.
- Transfer OP in plan to xt in front view. Join o't' by straight line. o't' is the true length of slant edge.
- With 'O' as centre draw the development of whole pyramid. (Follow the steps of the exercise 10)
- With 'O' as centre set off OA, OB, OC, OD & OA equal to O'U' in front view. (Fig 9c)
- Join AB, BC, CD, DA. Surface bounded by ABCDATSRQP is the development.

10 Draw the development of the lateral surface of a funnel as positioned. (Fig 10)




- The parts (A & B) of the funnel are in the shapes of frustum of cones.
- Development of cone and frustum of cone are already dealt in earlier exercises. Follow the previous procedures and draw the developments of both parts A and B.


Formula for finding angle

$$\alpha = \frac{\text{Radius of base cone circle}}{\text{Slant height}} \times 360^\circ$$

11 The cylinders A & B are positioned as shown, (Fig 11) intersects each other at right angles. Draw the plan, elevation, side view and show the curve of intersection.



12 Draw the three views of cylinder 'A' as shown in position. (Fig 12)



- Draw the side view of the cylinder 'B', as circle of diameter equals to 40 mm, such that its centre is the mid-point of the axis of cylinder 'A'.
- Divide the circle into 12 equal parts and number them.
- Draw the front view and top view of cylinder 'B' projecting from the side view of the horizontal cylinder.

Note: Consider that a number of horizontal section planes passing through the generators of the horizontal cylinder to cut both cylinders. For all the horizontal sectional planes, the sectional top view will always be a circle of 'n' diameter. Also the sectional top view of the vertical cylinder will be a circle of 'm' diameter.


- Draw series of cutting planes on the end view of cylinder 'B'.

- Draw horizontal projectors on to the vertical cylinder (A).
- The line 1 - 1₁ in top view intersects the circle at p₁ & q₁.
- Draw vertical projectors from these intersection points P₁ & q₁ to intersect the line 1'1', in front view at p'₁ and q'₁ respectively.
- Considering the second horizontal plane 2 2₁ in top view, obtain the corresponding point in the front view P'₂ (p'₁₂, q'₁₂) and q'₂.
- Repeat the same procedure for other series of section planes passing through generators, obtain intersection points in front view.

Join the obtained intersection points in the front view by a smooth curve, which is the curve of intersection of cylinders A & B as stated.


Dimensioning - Types of arrow heads and leader line with text

Dimension line: These are thin continuous lines, terminated at ends by arrowheads, dots or oblique lines touching the extension line. (Fig 1)



A dimension line may cut or cross another dimension line where there is no other way.

Dimension to the hidden lines be avoided. (Fig 2)



Arrowheads may be placed outside where space is insufficient.

Leader line: It is a thin continuous line. It connects a note or dimension with the features to which it applies. (Fig 2)

Termination and Origin indication: The size of the terminations (arrowheads/oblique strokes) shall be proportional to the size of the drawing. Only one style of arrowhead shall be used on a single drawing. However, where the space is too small for the arrowheads, it may be substituted by a dot or by an oblique line. Arrowheads are drawn as short lines forming barbs at any convenient

included angle between 15° and 90°. They may be open, closed or closed and filled in. Oblique strokes are drawn as short lines inclined at 45°. (Fig 1)

Indicating dimensional values on drawings: All dimensional values shall be shown on drawings in characters of sufficient size to ensure complete legibility on the original drawings as well as on reproductions made from micro-filming.

They shall be placed in such a way that they are not crossed or separated by any other line on the drawing.


Dimensioning - Position of dimensioning (aligned, unidirectional)

Definitions related to dimensioning

Dimension: It is a numerical value expressed as an appropriate unit of measurement and indicated graphically on technical drawings with lines, symbols and notes.

Size dimensions: Gives the size of a component, part, hole, slot, depth, width, radius etc.


eg: L1, L3, H, h1, S etc. (Fig 1)




Location dimension: Gives or fixes the relationship of the features. viz centre of holes, slots and any significant forms. (Fig 1)

eg: L4, L5, L6

Feature: It is an individual characteristic such as a flat surface. Cylindrical surface, shoulder, screw thread, a slot, a curve or profile etc. (Fig 2)



Extension line: It is a thin line projecting from the feature and extending beyond the dimension line. (Fig 3)




Methods of indicating values

Methods of indicating values: There are two methods used for indicating the values. Only one method should be used on anyone drawing.


Method 1 Aligned system

Dimensional values shall be placed parallel to their dimension lines and preferably near the middle, above and clear of the dimension line. However, values shall be indicated so that they can be read from the bottom of the drawing. Dimension lines should not be broken. Dimensioning of angles is also given in the same way. (Fig 1) This method is known as an **aligned system** of dimensioning.



Method 2 Unidirectional system

Dimensional values shall be indicated so that they can be read from the bottom of the drawing sheet. Non-horizontal dimension lines are interrupted, preferably near the middle so that the value can be inserted. (Fig 2). This method is termed a **unidirectional system** of dimensioning.




Arrangement and indication of dimensions

The arrangement of dimensioning on a drawing shall indicate clearly the design purpose.

The arrangements of dimensioning are:

- Chain dimensioning
- Dimensioning from a common feature
- Dimensioning by co-ordinates
- Combined dimensioning.


Chain dimensioning: It is used where the possible accumulation of tolerances does not infringe (effect) on the functional requirement of the component. (Fig 3)




Dimensioning from a common feature is used where several dimensions of the same direction relate to a common origin.

Dimensioning from a common feature may be executed as parallel dimensioning or as superimposed running dimensioning.

Parallel dimensioning: Dimensions of features are taken from one datum/common origin and are shown parallel to another and placed so that the dimensional values can easily be added in Fig 4.





Combined dimensioning: Dimensions are given in chain dimensioning and parallel dimensioning. The common feature is combined. (Fig 5)




Dimensioning a chord: For dimensioning of the chord, refer Fig 6. It is shown as linear size.


Dimensioning an arc/radius: A small arc is shown over the dimension value, while dimensioning an arc. (Fig 7)



When the drawing is clear, symbols or abbreviation viz. dia, Pcd and angle can be omitted. (Fig 8)




Dimensioning periphery: The features on the periphery can be shown as given in the figure, indicating width, depth and number of slots. (Fig 9)




Practice of dimensioning


- 1 To the given drawing of the profile sheet metal as shown in Fig 1, place the dimensions in the aligned system. (Fig 1a)
- Draw the drawing of the sheet metal to 1:1 scale.
 - Draw the extension lines in continuation of outlines.
 - Draw the dimension lines. (Fig 1b)
 - Place the dimension value near the middle and above the dimension line to be read from "bottom and right hand side" of the drawing.



- 2 To the given drawing of the profile sheet metal as shown in Fig 2a, give the dimensions in the unidirectional system. (Fig 2b)
- Place the horizontal dimensions above and middle of the dimension line without break.
 - Break the dimension in the middle of all non-horizontal dimension lines. (Fig 2b)





- 3 Draw the two sheet metal templates to full scale with appropriate lines use 0.5 range line thickness. (Fig 3)
- Draw a rectangular block of length 80 mm and width 50 mm in thin lines.
 - Incorporate the features of the template as per the given dimension.
 - Draw by thick lines all visible outlines.
 - Give dimensions and maintain the line thickness as per the line range (0.5).
 - Complete the figure and remove the unwanted lines.




- 4 Draw the figures given. Maintain the types of lines as per the B.I.S and choose correct line thickness. (Fig 4)
- According to the given dimensions, draw the figures given in Fig 4.
 - Select the appropriate lines and maintain uniformity.
 - Remove (erase) unwanted lines, arcs and complete the drawing.

Note: Draw the dimension line terminations as per IS:11669-1986.


- 5 The motor cycle engine gasket is shown in figure 5. There are some mistakes in dimensioning. Reproduce the same in the A3/A4 sheet provided and correct the mistakes according to the aligned system of dimensioning. (Fig 5)



6 Draw the given cover plate and give the dimensions in the aligned system. (Fig 6)




7 Draw the cover plate given in the figure and place the dimensions in the unidirectional system. (Fig 7)



Concept and reading of drawing in - Concept of axes plane and quadrant

An engineering drawing conveys many different types of information of which the most important thing is the shape of the object. Fig 1 shows a sample drawing. In this drawing, the shape of the part is represented by three views.



For an untrained person, it will be very difficult to conceive the shape of the object from the above drawing.

But in Fig 2, the same object is shown pictorially in a different way and the shape is easily understood even by a layman.






Figure 1 is called a Multiview drawing or Orthographic drawing and figure 2 is called a pictorial drawing.

Fig 3, wherein a cube with a circular hole is represented pictorially. We know that all corners of the cube are 90°. But in the pictorial drawing in Fig 3, the same 90° is represented at some places by acute angles and some other places by obtuse angles.




Projection: Projection is a commonly used term in draughtsman's vocabulary. In the context of engineering drawing, projectors mean images.

Projections or images can also be formed in between the eyes and the object by keeping a transparent plane. (Fig 4)




In this figure 4, the rays from the object converge to the eyes and this image (Projection) is smaller than the object. However, if the rays are parallel as in the case of rays coming from the sun, the image (Projection) will be of the same size as that of the objects. Such a projection is called

orthographic projection. The parallel lines/rays drawn from the object are called projectors and the plane on which the image is formed is called the plane of projection. In orthographic projection, the projectors are perpendicular to the plane of projection. (Fig 5)



An orthographic system of projection is the method of representing the exact shape and size of a three-dimensional object on a drawing sheet or any other plain surface such as a drawing board.

A single orthographic view of an object will show only two of its three dimensions. The view in figure 6 shows only the length and height of the object alone.




Therefore, it becomes necessary to have an additional view to show the missing dimensions (width). Hence, we have to make two views to represent the three dimensions of an object.

The two views thus required are to be obtained on two different planes which are mutually perpendicular (one HP and one VP) with the object remaining in the same position. The projection or the view obtained on the horizontal plane is called the top view or plan and the view obtained on the vertical plane is called elevation.



First angle and third angle projection: One vertical plane (VP) and one horizontal plane (HP) intersect at right angles to each other. (Fig 7)

All four quadrants have one HP and one VP formation. As per convention in mathematics, the quadrants are numbered as 1st, 2nd, 3rd and 4th. These four quadrants are called four dihedral angles, namely 1st angle, 2nd angle, 3rd angle and 4th angle.






To draw two views of an object, we assume that the object is placed in any one of the quadrant/angles, 1st angle & 3rd angle (Fig 8a & 9a) and its top and front view are projected to the respective planes.

Now to make it possible to draw the two views (Front & Top view) in one plane i.e the plane of the drawing paper, the horizontal plane is assumed to be unfolded in a clockwise direction through 90° (Fig 8b & 9b). We proceed this way when the views are made. When the object is placed in the 2nd or fourth quadrant the front and top will get superimposed (one upon the other) (Fig 10a & b).



Due to this reason, the 2nd and 4th angles are not used for making engineering drawings as the three dimensions cannot be easily identified. Hence for representing the three dimensions of the object, we assume the object is placed either in the 1st angle or in the 3rd angle (Fig 11&12) respectively.




Concept and reading of drawing in - Concept of orthographic projection and isometric projection

Concept of Orthographic projection

Method 1

Draw the orthographic projection (front, top and side views) of the square sheet (40 mm side) kept perpendicular to HP and parallel to VP. (I angle) (Fig 1)




- Draw the XY line.
- Draw the square with its centre 40 mm above the XY line and one edge parallel to the XY line.
- Mark the corners of the figure a', b', c' & d'. This will be the front of the square.
- Draw the vertical projectors from a'b' downward beyond the XY line.
- Draw a horizontal line dc at a distance of 20 mm below the XY line. Line dc will be the plan.
- Draw a X'Y' line at a convenient distance from b'c', intersecting the XY line at 'O'.
- Project the top to the X Y line meeting at e.
- By arc method transfer Oe to XY and mark the point 'f' at a'' and d'' respectively. Now the line a''d'' is the side view.

Method 2: Rectangular prism

Draw the Top, Front and side views of the rectangular prism of base 30 x 20 mm and height 40 mm. (Fig 2A)

In this exercise, the faces of the prism are parallel to the planes of projection. Therefore all the line's orthographic projections are vertical and horizontal only.

Visualise the shape of the object and imagine the shape description of views. Surface ABCD (Fig 2B) is only visible from the elevation. At the same time, all four sides of ABCD are isometric lines. Therefore in the elevation, a rectangle of 40 x 30 mm is seen.




- Draw XY line of convenient length. (Fig 2B)
- Draw a rectangle a'b'c'd' on the XY line. This will be the front view of the prism.
- Project the vertical sides of the front view (a'd' and b'c') downwards beyond the XY line.
- Draw a horizontal line fg approximately 20 mm below the XY line.

- Draw a rectangle fgba of 30 x 20 mm size. This will be the plan of the prism.
- Project points b' and c' horizontally a convenient length to the right side of the elevation.
- Transfer the width of the top view GB by the arc and locate points e" d" on the XY line.
- Project e" d" vertically up and locate points f' a" d" e" is the left side view of the prism.

Method 3 : Cylinder

Draw the top, front and side view of a cylinder of diameter 20 mm and length of 30 mm. (Fig 3A)




In this problem, the circular faces are parallel to VP. Therefore the front is a circle resting on the XY line. Plan and end views are rectangles of size 30 mm x 20 mm.

- Draw the circle of diameter 20 mm touching the XY line. (Fig 3B)
- Draw the plan projecting it from the elevation.
- Draw the end view by drawing a projection on it, from the plan and elevation.
- Draw the top, front and side views of a cylinder whose base diameter is 35 mm and height 50 mm when its position is as shown in Fig 3C.

Method 4: Cone

Draw the multi-views of the cone shown in Fig 4A. Follow the procedures of the earlier exercises and draw the multi-views. (Fig 4B)







Method 5

Identify the surfaces of the block shown in the isometric view with the corresponding multi-views and fill the numerals in the given tabulation column. (Fig 5)

The surfaces are parallel and perpendicular to the plane of projection.

- Study the isometric view and the corresponding multi-views carefully.

Fig 5



| | F | S | P |
|---|---|---|----|
| A | 5 | 6 | 10 |
| B | | | |
| C | | | |
| D | | | |
| E | | | |
| F | | | |

- You may observe that the surfaces seen in one view are represented by lines in the other two views.
- In this exercise, the surface 'A' shown in the isometric view is seen as a line in the front elevation and numbered as '5' in the front view of the corresponding multi-views.
- The same surface 'A' in the side view is seen as a line and numbered '6' in the side view of the multi-views.
- Similarly, the surface 'A' seen from the top of the isometric views is numbered as '10' in the plan of the multi-views, whereas the full surface area is visible.

When a surface is parallel or perpendicular to the plane of projection vice-versa in a multi-views drawing, the full area of the surface will be seen in anyone the three views (plan, elevation and side view) and in the other two views, the corresponding line of the surface will be seen.

Method 6

Draw the isometric view (Fig 6) and also draw the three views in the workbook.

The orthographic projection shows the shape of a component by drawing several views each looking at a different side of the component.

A minimum of two views are required to represent a component. To clarify the internal and external details a minimum of three views are to be drawn. They are:

- Elevation or Front view or Front elevation. (F)
- Plan or Top view. (P)
- Side view or side elevation or end elevation. (S)

In Fig 6, surface 'A' is only seen when looking at the front of the figure. All the lines in the isometric view are isometric. Therefore in the orthographic projection, the front view will be like this. (Fig 7)

In the plan surfaces 'C', 'D' and 'F' are visible and the bottom surface will not be visible. The line joining the two surfaces will not be visible. The line joining the surfaces will appear in the plan as a hidden line. (Fig 8)

In the side view surface 'B' is visible and surfaces 'E' and back bottom surfaces are invisible. Due to this reason the line joining 'D' and 'E', also the line joining back bottom surfaces are appearing in the side view by a hidden line. (Fig 9)

Fig 6




Fig 7




Fig 8





Fig 9



Pictorial drawing (isometric drawing)


Pictorial drawing: Even a common man can understand easily the shape of an object quickly by a picture or by a pictorial drawing. It is also called three-dimensional drawing.

Pictorial drawings are very useful for describing the shape of a piece part or component, even though they have a distorted look.

Three types of pictorial drawings are (Fig 1)

- Isometric drawing
- Oblique drawing
- Perspective drawing

Out of the above three types, isometric drawings are very much preferred by machine shops and metalworking trades groups. But perspective drawings are popular in the civil engineering group of trades.




Isometric drawing

Procedure

1 Rectangular prism

Draw the isometric drawing of a rectangular prism of base 15 mm x 30 mm and the height of 50 mm. (Fig 1)


- Draw the three isometric axes through point 'A'.
- Mark AB = 15 mm, AD = 30 mm and AH = 50 mm representing the three sides of prism.



- Draw two vertical lines parallel to the line AH through points B and D.
- Similarly draw two more lines parallel to AB and AD through point H.
- Mark G and E the intersecting points.
- Draw lines parallel to GH and HE through points G and E intersecting point is F.
- Draw lines parallel to AB & AD through points D and B respectively intersecting at C.
- Join CB & CD with dash lines.
- Join F and C also with dash lines.
- Rub off the construction lines and complete the prism.

2 Stepped block - 1

Draw the isometric view of the stepped block given in Fig 2.




- Draw the isometric view of a rectangular prism of dimensions equal to the overall size of the block 45 x 25 x 30 mm.
- Draw the lines JD, DE, EF, FH, HI and IJ using the measurements given in the figure.
- Rub off SR, RD, SJ, SH and RF.
- Darken the remaining lines of the stepped block.

3 Stepped block - 2

Draw the isometric view of the components shown. (Fig 3)



- Draw the stepped block as per dimension. Follow the procedure given in the previous Ex. No.2.
- Mark points to UTSV as per dimension on the top of the surface EDGF (Fig 3b)
- Join points UTSV.
- Project vertically downwards from the points UTSV and obtain the point WXYZ at the bottom surface such that UW, TX, SY & VZ are equal to 10 mm. Join the point WXYZ and draw the thick lines which are all visible and dotted lines that are not visible

All construction lines should be in thin lines. After completion of the isometric views, in each case erase the unwanted lines and construction lines.




With the experiences gained in previous exercises of drawing isometric views, draw the following exercises 4 & 5 and complete the same.

Practice 1 to 3 (Figs 4,5 &6)




Draw the isometric view of the machined block having non-isometric lines. (Fig 6)



Method of 1st angle and 3rd angle projections (Definition and difference)

Symbol of 1st angle and 3rd angle projection as per IS specification




- 1 a Draw the symbol for 1st angle projection as per IS specification, if bigger dia D is 50 mm.
- b Draw the symbol for 3rd angle projection as per IS specification, if bigger dia D is 40 mm.


- 2 a Draw the symbol for 1st angle projection as per IS specification, if smaller dia D/2 is 20 mm.
- b Draw the symbol for 3rd angle projection as per IS specification, if smaller dia D/2 is 15 mm.

Method of 1st angle and 3rd angle projections

1st Angle projection (Fig 1)






3rd Angle projection (Fig 2)













The two views thus required are to be obtained on two different planes which are mutually perpendicular (one HP and one VP) with the object remaining in the same position. The projection or the view obtained on the horizontal plane is called the top view or plan and the view obtained on the vertical plane is called elevation.





The placement of the front and top views when the horizontal plane is unfolded will be different in these two systems. It may be observed in Fig 3, that the first angle projection plan (top views) will be directly below the front view (Fig 4), whereas in 3rd angle projection top view lies directly above the elevation. (Fig 5)

Views can be drawn in any one of these two methods. However Indian Standard (BIS) has recommended the first angle method to be used in our country.




Symbolic representation - Different symbols used in the sheet metal trade






Different operations of bend by press brake (Fig 15)




Practice on snap locked seam (Fig 16)



Reading of job drawing related to sheet metal trade


Read and write the following. (Fig 1)

- 1 Which type of notch used for making rectangular box?
- 2 What is the name of joining?
- 3 What is the purpose of notch?




Read and write the following. (Fig 2)

- 1 What are the joints are in Duct work?
- 2 What are the folding in the ducting and write the name?
- 3 What are the bending in duct and write the name?
- 4 What is the use of duct?




Read and write the following. (Fig 3)

- 1 What is the types of notch?




Read and write the following. (Fig 4)

- 1 What type of notch used in the Fig 4?
- 2 What is the name of activity?




Read and write the following. (Fig 5)

- 1 What is the name of Duct?




Read and write the following. (Fig 6)

- 1 Where rectangular duct used?
- 2 Why the ridges are provided in the duct?




Read and write the following. (Fig 7)

- 1 What is the name of joint 'A'?
- 2 What is the name of joint 'B'?



Read and write the following. (Fig 8)


- 1 What is the name of the joint 'A'?



Read and write the following. (Fig 9)


- 1 Write the name of 'A'?
- 2 Write the name of 'B'?
- 3 Write the name of 'C'?

- 4 Write the name of 'D'?
- 5 Write the name of 'E'?
- 6 Write the name of 'F'?




Read and write the following. (Fig 10)

- 1 Why G.I wire to be inserted?




Read and write the following. (Fig 11)

- 1 What is the name of activity?




Read and write the following. (Fig 12)

- 1 What is the name of hammer?
- 2 What is the name of tool 'A'?




Read and write the following. (Fig 13)

- 1 What is the angle of slant notch?




Read and write the following. (Fig 14)

- 1 What is the name of 'C'?
- 2 What is the name of 'D'?
- 3 What does X refers?




Read and write the following. (Fig 15)

- 1 What is the name of joint?
- 2 What does $\frac{1}{2}T$ refers?




Read and write the following. (Fig 16)

- 1 What is the name of joint?
- 2 What is the angle of 'A'?




Read and write the following. (Fig 17)

- 1 What is the name of joint?
- 2 What is the angle of joint?




Read and write the following. (Fig 18)

- 1 What is the name of joint?




Read and write the following. (Fig 19)

- 1 What is the meaning of flange joint?



Read and write the following. (Fig 20)

- 1 What is the name of bend?
- 2 What is the angle of 'A'?
- 3 What is the angle of 'B'?




Read and write the following. (Fig 21)

- 1 What is the name of joints 'A'?
- 2 What is the name of joints 'B'?

- 3 What is the name of joints 'C'?
- 4 What is the name of joints 'D'?
- 5 What is the name of joints 'E'?

Fig 1



EDNSM162321